## SPECIALISTS IN ELECTRONIC & ELECTROMECHANICAL ROOT CAUSE FAULT FINDING AND RESOLUTION

### **Problem - Traction inverters**

Our customer had a problem with ageing Frequency Division Multiplexer (FDM) racks. Resulting in service delays. They were looking for assistance in scoping an overhaul programme to provide maximum benefit.



# **Challenges for SET**

- Additional float stock was required to support the overhaul.
- Equipment contains various obsolete and custom components.
- Safety case was complex for fit, form and function replacement.
- 3 parties involved in the overhaul



### **Proposal**

- Technical report produced, based on analysis of the design and historical repair data.
- Several costed options offered, along with rationale for each.

### Result

- SET's proposal selected
- 20 fit, form and function units produced and approved for use.
- New design was independently audited and approved by SNC Lavalin.

Atlas Works, Litchurch Lane, Derby DE24 8AQ

Tel: +44 (0) 1332 346 035 info@set-gb.com www.set-gb.com