

SPECIALISTS IN ELECTRONIC & ELECTROMECHANICAL ROOT CAUSE FAULT FINDING AND RESOLUTION

Problem - Inverter handling Health & Safety issue

A high risk handling activity had been identified at the customer's depot where engineers have to invert traction packs before fitting.



Solution

- SET designed and manufactured a turning rig.
- SET specified and had produced a set of customised packing cases that ensured that equipment arrived at the depot the correct way up for their processes.



Result

- The risk due to turning the equipment on-site was removed.